



AMI Software Utility Release Notes

Aptio 5.x AFU Release Notes

Document Revision 1.15

April 22, 2019



Confidential, NDA Required
Copyright © 2019

American Megatrends, Inc.
5555 Oakbrook Parkway
Suite 200
Norcross, GA 30093 (USA)

All Rights Reserved
Property of American Megatrends, Inc.

Legal

Disclaimer

This publication contains proprietary information which is protected by copyright. No part of this publication may be reproduced, transcribed, stored in a retrieval system, translated into any language or computer language, or transmitted in any form whatsoever without the prior written consent of the publisher, American Megatrends, Inc. American Megatrends, Inc. retains the right to update, change, modify this publication at any time, without notice.

For Additional Information

Call American Megatrends, Inc. at 1-800-828-9264 for additional information.

Limitations of Liability

In no event shall American Megatrends be held liable for any loss, expenses, or damages of any kind whatsoever, whether direct, indirect, incidental, or consequential, arising from the design or use of this product or the support materials provided with the product.

Limited Warranty

No warranties are made, either expressed or implied, with regard to the contents of this work, its merchantability, or fitness for a particular use. American Megatrends assumes no responsibility for errors and omissions or for the uses made of the material contained herein or reader decisions based on such use.

Trademark and Copyright Acknowledgments

Copyright © 2019 American Megatrends, Inc. All Rights Reserved.

American Megatrends, Inc.
5555 Oakbrook Parkway
Suite 200
Norcross, GA 30093 (USA)

All product names used in this publication are for identification purposes only and are trademarks of their respective companies.

Table of Contents

Document Information	6
Description	6
Change History	6
Introduction	7
Overview	7
Requirements	7
BIOS Requirements	7
Supported Operation System	7
Source Control Location	7
Windows	7
Linux	7
EFI Shell	7
Limitations	7
Release Version	8
Latest Release	8
Ver. 5.12.01.1977 2019-04-22	8
New Features	8
Issues Fixed	8
Update Module	8
Ucore2 Module	8
Version History	8
Ver. 5.12.00.1939 2019-03-06	8
New Features	8
Update Module	8
PLDM Library List	8
Ucore2 Module	9
Ver. 5.12.00.1904 2019-01-28	9
New Features	9
Update Module	9
PLDM Library List	9
Ucore2 Module	9
Ver. 5.11.06.1854 2018-11-28	10
New Features	10
Issues Fixed	10
Ver. 5.11.05.1840 2018-11-06	10
New Features	10
Issues Fixed	10
Update Module	10
Ver. 5.11.04.1806 2018-10-05	10
New Features	10
Rule Changes	10
Update Module	10

Ver. 5.11.03.1778	2018-08-31	10
Issues Fixed		10
Ver. 5.11.02.1769	2018-08-28	10
Issues Fixed		10
Ver. 5.11.02.1762	2018-08-09	11
Issues Fixed		11
Rule Changes		11
Ver. 5.11.01.1745	2018-07-19	11
New Features		11
Issues Fixed		11
Feature Enhancement		11
Ver. 5.11.00.1727	2018-06-28	11
New Features		11
Ver. 5.10.02.1690	2018-05-31	11
New Features		11
Issues Fixed		11
Rule Changes		12
Ver. 5.10.01.1670	2018-04-23	12
New Features		12
Issues Fixed		12
Rule Changes		12
Ver. 5.10.01.1648	2018-03-29	12
Issues Fixed		12
Rule Changes		12
Ver. 5.10.00.1615	2018-02-12	12
Issues Fixed		12
Ver. 5.10.00.1610	2018-02-09	12
New Features		12
Driver Updates		13
Rule Changes		13
Issues Fixed		13
Ver. 5.09.04.1540	2017-12-01	13
New Features		13
Ver. 5.09.04.1503	2017-10-16	13
New Features		13
Rule Changes		13
Issues Fixed		13
Update Library		14
Ver. 5.09.03.1470	2017-09-11	14
New Features		14
Ver. 5.09.03.1466	2017-09-04	14
Issues Fixed		14
Ver. 5.09.03.1456	2017-08-17	14
Rule Changes		14
Ver. 5.09.03.1452	2017-08-02	15
Issues Fixed		15
Ver. 5.09.03.1448	2017-07-28	15
New Features		15
Rule Changes		15
Ver. 5.09.03.1445	2017-07-20	15
New Features		15
Rule Changes		15
Issues Fixed		15

Ver. 5.09.02.1396	2017-05-25	15
Rule Changes		15
Ver. 5.09.02.1384	2017-05-05	16
New Features		16
Rule Changes		16
Issues Fixed		16
Ver. 5.09.01.1319	2017-01-13	16
Issues Fixed		16
Ver. 5.09.01.1317	2017-01-13	16
New Features		16
Rule Changes		16
Issues Fixed		16
Functions Improved		16
Ver. 5.09.00.1284	2016-11-01	17
New Features		17
Rule Changes		17
Issues Fixed		17
Ver. 5.08.02.1189	2017-04-27	17
New Features		17
Rule Changes		17
Issues Fixed		17
Ver. 5.08.01.1167	2017-04-27	17
Issues Fixed		17
Ver. 5.08.01	2016-02-26	18
New Features		18
Rule Changes		18
Issues Fixed		18
Ver. 5.08.00	2015-06-26	18
New Features		18
Rule Changes		18
Issues Fixed		18
Ver. 5.07.01	2015-02-03	19
New Features		19
Rule Changes		19
Issues Fixed		19
Ver. 5.07.00	2014-11-18	19
New Features		19
Rule Changes		19
Issues Fixed		19
Ver. 5.06.01	2014-04-25	20
New Features		20
Rule Changes		20
Issues Fixed		20
New Message		20
Ver. 5.06.00	2014-03-24	20
Rule Changes		20
Issues Fixed		20
Change Message		20
Ver. 5.05.04	2014-01-24	21
Issues Fixed		21
Ver. 5.05.03	2013-11-12	21
Rule Changes		21
Issues Fixed		21

Document Information

Description

This document provides release information of AptioV AFU tool.

Change History

Date	Revision	Description
2018-02-09	1.00	Initial draft created and using one format for Release Notes.
2018-02-12	1.01	Update for AFU v5.10.00.1615 release.
2018-03-29	1.02	Update for AFU v5.10.01.1648 release.
2018-04-23	1.03	Update for AFU v5.10.01.1670 release.
2018-05-31	1.04	Update for AFU v5.10.02.1690 release.
2018-06-28	1.05	Update for AFU v5.11.00.1727 release.
2018-07-19	1.06	Update for AFU v5.11.01.1745 release.
2018-08-09	1.07	Update for AFU v5.11.02.1762 release.
2018-08-28	1.08	Update for AFU v5.11.02.1769 release.
2018-08-31	1.09	Update for AFU v5.11.03.1778 release.
2018-10-05	1.10	Update for AFU v5.11.04.1806 release.
2018-11-06	1.11	Update for AFU v5.11.05.1840 release.
2018-11-28	1.12	Update for AFU v5.11.06.1854 release.
2019-01-21	1.13	Update for AFU v5.12.00.1904 release.
2019-03-06	1.14	Update for AFU v5.12.00.1939 release.
2019-04-22	1.15	Update for AFU v5.12.01.1977 release.

Introduction

Overview

AFU(AMI Firmware Update) is a package of utilities used to update the system BIOS under various operating systems. AFU only works for APTIO with SMI FLASH support.

Requirements

BIOS Requirements

- Aptio 5 or later.
- Requires that the currently installed firmware has SMI flashing support enabled.

Supported Operation System

- AFUWIN (AFUWIN.EXE/ AFUWINx64.EXE/ AFUWINGUI.EXE/ AFUWINGUIx64.EXE) are supported in Windows NT/ 2000/ XP/ 2003/ Server 2008 R2/ 2012 R2/ PE/ Vista/ 7/ 8/ 8.1/ 10.
- AFUEFI (AFUEFI.EFI/ AFUEFIx64.EFI) are supported in EFI Shell.
- AFULNX (afulnx_32/ afulnx_64) are supported in Linux operation system.

Source Control Location

Windows

SS: AptioV;\$/AptioV/RomUtils/Afu/AfuWin/64;
SS: AptioV;\$/AptioV/RomUtils/Afu/AfuWin/32;

Linux

SS: AptioV;\$/AptioV/RomUtils/Afu/AfuLnx/64;
SS: AptioV;\$/AptioV/RomUtils/Afu/AfuLnx/32;

EFI Shell

SS: AptioV;\$/AptioV/RomUtils/Afu/AfuEFI/64;
SS: AptioV;\$/AptioV/RomUtils/Afu/AfuEFI/32;

Limitations

- None

Release Version

Latest Release

Ver. 5.12.01.1977

2019-04-22

New Features

- Added AFU can support SSB command by AMD Combo AM4 platform.
- Added AFU checks OFBD ROM ID error message.

Issues Fixed

- Fixed an issue where AFU Linux failed to load the driver on the PenDrive.
- Fixed an issue where AFU display help menu does not display ME region commands.[EIP458269]
- Fixed an issue where secure flash is disabled, AFU does not force a check write-once rule.[EIP454946]
- Fixed an issue where NonBIOS_Validation token enabled, need can support backward compatibility.

Update Module

- Updated the version of supporting Faster Deployment of Security Patches feature to REF-51368-SourceChange V3.[EIP459963]

Ucore2 Module

- Updated Ucore2 Module to Trunk1981.

Version History

Ver. 5.12.00.1939

2019-03-06

New Features

- Added AFU can support ME to push data retry.

Update Module

- Updated the version of supporting Faster Deployment of Security Patches feature to V6_2 [EIP436131]
- Updated Windows driver.
- Updated PLDM SCE Library.

PLDM Library List

- UefiLib 32:
SceEfiLib32.lib =>
\$/AptioV/RomUtils/Eta2/Binary/Modules/AmisceAfu/SceEfi/Ia32;(INT)SceEfi32_5_03_1125
- UefiLib 64:
SceEfiLib64.lib =>
\$/AptioV/RomUtils/Eta2/Binary/Modules/AmisceAfu/SceEfi/X64;(INT)SceEfi64_5_03_1125

- WinLib 32:
SceWinLib32.lib =>
\$/AptioV/RomUtils/Eta2/Binary/Modules/AmisceAfu/SceWin/Ia32;(INT)SceWin32_5_03_1125
- WinLib 64:
SceWinLib64.lib =>
\$/AptioV/RomUtils/Eta2/Binary/Modules/AmisceAfu/SceWin/X64;(INT)SceWin64_5_03_1125
- LnxLib 32:
SceLnxLib32.lib =>
\$/AptioV/RomUtils/Eta2/Binary/Modules/AmisceAfu/SceLnx/Ia32;(INT)SceLnx32_5_03_1125.2
- LnxLib 64:
SceLnxLib64.lib =>
\$/AptioV/RomUtils/Eta2/Binary/Modules/AmisceAfu/SceLnx/X64;(INT)SceLnx64_5_03_1125.2

Ucore2 Module

- Updated Ucore2 Module to Trunk1938.

Ver. 5.12.00.1904

2019-01-28

New Features

- Added AFU can support ME to push data retry.

Update Module

- Updated the version of supporting Faster Deployment of Security Patches feature to V6_2 [EIP436131]
- Updated Windows driver.
- Updated PLDM SCE Library.

PLDM Library List

- UefiLib 32:
SceEfiLib32.lib =>
\$/AptioV/RomUtils/Eta2/Binary/Modules/AmisceAfu/SceEfi/Ia32;(INT)SceEfi32_5_03_1125
- UefiLib 64:
SceEfiLib64.lib =>
\$/AptioV/RomUtils/Eta2/Binary/Modules/AmisceAfu/SceEfi/X64;(INT)SceEfi64_5_03_1125
- WinLib 32:
SceWinLib32.lib =>
\$/AptioV/RomUtils/Eta2/Binary/Modules/AmisceAfu/SceWin/Ia32;(INT)SceWin32_5_03_1125
- WinLib 64:
SceWinLib64.lib =>
\$/AptioV/RomUtils/Eta2/Binary/Modules/AmisceAfu/SceWin/X64;(INT)SceWin64_5_03_1125
- LnxLib 32:
SceLnxLib32.lib =>
\$/AptioV/RomUtils/Eta2/Binary/Modules/AmisceAfu/SceLnx/Ia32;(INT)SceLnx32_5_03_1125.2
- LnxLib 64:
SceLnxLib64.lib =>
\$/AptioV/RomUtils/Eta2/Binary/Modules/AmisceAfu/SceLnx/X64;(INT)SceLnx64_5_03_1125.2

Ucore2 Module

- Updated Ucore2 Module to Trunk1901.

Ver. 5.11.06.1854**2018-11-28****New Features**

- Added AFU can support OEM ME region.[EIP437754]

Issues Fixed

- Fixed issue where the user uses /ME command in not support signature ME platform, but the signature ME function uploaded the ROM file.
- Fixed issue where the user uses /MEUL:<BIN> /capsule for capsule update, AFU will show 0x58 error.

Ver. 5.11.05.1840**2018-11-06****New Features**

- Added AFU can support AMD 32MB Rom File.[EIP432032]

Issues Fixed

- Fixed issue where PLDM feature doesn't work when user uses command /q for capsule update in EFI Shell environment.[EIP440501]
- Fixed issue where the user did not use the /ME related command, but the signature ME function uploaded the ROM file.

Update Module

- Updated the version of supporting Faster Deployment of Security Patches feature to V6 [EIP436131]

Ver. 5.11.04.1806**2018-10-05****New Features**

- Added 2 AFU commands for capsule and recovery with Intel BIOS Guard Technology. [EIP433668]
- Added AFU can support signed ME firmware update under Run Time state. [EIP402390]

Rule Changes

- Changed command /pw which will not check the returned password length from BIOS.

Update Module

- Updated the version of supporting Faster Deployment of Security Patches feature to V5 [EIP436131]

Ver. 5.11.03.1778**2018-08-31****Issues Fixed**

- Fixed issue where AFU flash use command /p /b will show verify fail error.

Ver. 5.11.02.1769**2018-08-28****Issues Fixed**

- Fixed issue where AFU show version.

Ver. 5.11.02.1762**2018-08-09****Issues Fixed**

- Fixed issue where PLDM feature doesn't work when ROM layout change with which users select option (F). [EIP420604]
- Fixed issue where AFU cannot look for ROMHOLE when the position of ROMHOLE in different FV. [EIP424921]

Rule Changes

- Changed to support that PLDM feature will not work when ROM layout change with which users select option (E).
- Changed to support new ME check process. [EIP422582]
- Changed Faster Deployment of Security Patches feature.
- Changed to support command /meuf.

Ver. 5.11.01.1745**2018-07-19****New Features**

- Added a feature to support command /pw: on Gemini Lake and Apollo Lake platforms. [EIP414545]
- Added a feature to support command /e on Gemini Lake and Apollo Lake platforms. [EIP411848]
- Added Faster Deployment of Security Patches copy tool integration. [EIP406350]

Issues Fixed

- Fixed issue where AFU will result in system hang up after reading process has done on Gemini Lake platform. [EIP416683]
- Fixed issue where AFU will show "map warning" message if BIOS supports WSMT but Linux environment does not have Linux kernel source. [EIP415782]

Feature Enhancement

- Enhanced the mechanism where PLDM feature cannot be used by AFU Linux on OEM Purley platform. [EIP403785]

Ver. 5.11.00.1727**2018-06-28****New Features**

- Added OACU module support.[EIP380410]
- Added AFUWINGUI window can't be closed during flash via touch device.[EIP413403]

Ver. 5.10.02.1690**2018-05-31****New Features**

- Added command "/RLC:"[EIP412153]
- Added OFBD AFU log module.[EIP398221]
- Added a new support that DMI data can be saved in non boot block or main block. [EIP408706][EIP412149]

Issues Fixed

- Fixed issue where users input command usage "/me /s", AFU will not flash ME region. [EIP411273]

Rule Changes

- Changed to enable \CLNEVNLOG command.
- Changed that when flashing BIOS to remove OA key via disabling Secure flash, tool will not use the solution of write once to execute. [EIP404259]

Ver. 5.10.01.1670**2018-04-23****New Features**

- Added EFI_FIRMWARE_FILE_SYSTEM3_GUID condition to supports check ROM FV.

Issues Fixed

- Fixed issue where check BIOS + ME BIN file in Coffee Lake.

Rule Changes

- [LNX]Modified the order of Linux check ACPI table.

Ver. 5.10.01.1648**2018-03-29****Issues Fixed**

- Fixed issue where PS2 keyboard/mouse cannot be used normally under EFI Shell.
- Fixed issue where ROM Layout Change option list will not be displayed when commands are /capsule, /recovery, and /D.
- Fixed issue where AFU will not inspect ROM Layout Change if ROM file or on-board BIOS cannot be got ROM Layout FFS data. [EIP394360]

Rule Changes

- Changed title when ROM Layout Change, the title would become as following:
Press \"E\" - This option will update entire ROM and exit.
Press \"A\" - This option will be no ROM update.
Press \"F\" - This option will be forcing to follow the command by user provided.
- Modified to inspect the mechanism of BIN file of ME + BIOS. [EIP381008]
- [LNX]Modified the order of Linux loading driver. [EIP398938]

Ver. 5.10.00.1615**2018-02-12****Issues Fixed**

- Fixed issue OAD command can't delete OA Key.

Ver. 5.10.00.1610**2018-02-09****New Features**

- Added a mechanism that tool will provide 3 options, "(F)Force, (E)Exit, (A)All" when ROM layout change. [EIP353462]
- Added a scenario that is while performing APL and FTF EMMC mode, tool only can use /p /n /e /a
- Added 2 error messages in APL EMMC mode.
Error: EMMC Mode cannot be used runtime flash command, please use capsule or recovery to update BIOS.

Error: Capsule and Recovery command cannot be used together.

- Added OFBD OAKEY Statue Flag.
- Added OFBD OAKEY Func Flag.
- Added a mechanism that tool cannot use command /p /b /n to update BIOS in runtime flash if the system is EMMC.
- Added command /a in Fault Tolerance Flash EMMC mode. [EIP373363]
- Added command /OAD in Fault Tolerance Flash EMMC mode. [EIP373363]
- Added a retry mechanism for ME Flash. [EIP375769]
- Added to use Fault Tolerance Flash when Secure Flash is disabled. [EIP382585]
- Added a mechanism to detect BIN file size of "BIOS+ME". [EIP381008]
- Added command /pw: to general command list.
- Added more detailed descriptions of error message if parameter only has command /Recovery or /Capsule. [EIP353002]
- Added a string which is "Process completed" when a process has done successfully. [EIP385941]

Driver Updates

- [LNX] Added that tool supports Linux kernel 4.13. [EIP369928, EIP370558, EIP372572, EIP377663]

Rule Changes

- Changed Copyright to 2018.
- Removed command "/caf", "/clevnlog", and "/meuf".
- Changed the flash process of command /a. When OA is OA Block in single BIN file, the tool will skip the behavior of Reading Flash. [EIP350874]
- Changed the process of OA OFBD update under Fault Tolerance Flash EMMC mode. [EIP373363]
- Changed that AFU will not read SPI ROM data when the tool does ME flash individually.
- Changed command /A to /A:.
- [LNX] Changed that using Linux Driver to map ACPI table. [EIP379929]

Issues Fixed

- Fixed issue where using Flash Lib Read API ROM cannot retry. [EIP375769]
- Fixed issue where JBC cannot be used before adjusting the order of module.
- Fixed issue where reading NCB will cause the accumulation problem.
- [LNX] Fixed issue where UCP will show error message of UAF when users are loading AFU Linux.

Ver. 5.09.04.1540

2017-12-01

New Features

- [WIN] Added to support retry mechanism for ME flash.

Ver. 5.09.04.1503

2017-10-16

New Features

- Added to support Coffee Lake ME flash.

Rule Changes

- Changed if using command /p /n, AFU will do Flash All for APL platform.

Issues Fixed

- [WINGUI] Fixed issue where WINGUI ROM file ID and ROM file Path show garbled

Update Library

- Updated PLDM SCE Library

[PLDM Library List]

UefiLib 32:
NvramImageLibEfi.lib =>
\$/AptioV/RomUtils/Eta2/Binary/Modules/NvramLib/NvramLibEfi/Ia32;(INT)NvramLibEfi_STDLIB-1.0.2_9
SceEfiLib32.lib => \$/AptioV/RomUtils/Eta2/Binary/Modules/AmiSce/SceEfi/Ia32; (INT)SceEfi_5_03_1112
UefiLib 64:
NvramImageLibEfiX64.lib =>
\$/AptioV/RomUtils/Eta2/Binary/Modules/NvramLib/NvramLibEfi/X64;(INT)NvramLibEfi_STDLIB-1.0.2_9
SceEfiLib64.lib => \$/AptioV/RomUtils/Eta2/Binary/Modules/AmiSce/SceEfi/X64; (INT)SceEfi_5_03_1112
WinLib 32:
NVRAMImageLibWin.lib => \$/AptioV/RomUtils/Eta2/Binary/Modules/NvramLib/NvramLibWin/Ia32;
(INT)NvramLibWin-1.0.2_8
SceWinLib32.lib => \$/AptioV/RomUtils/Eta2/Binary/Modules/AmiSce/SceWin/Ia32; (INT)SceWin_5_03_1112
WinLib 64:
NVRAMImageLibWinX64.lib => \$/AptioV/RomUtils/Eta2/Binary/Modules/NvramLib/NvramLibWin/X64;
(INT)NvramLibWin-1.0.2_8
SceWinLib64.lib => \$/AptioV/RomUtils/Eta2/Binary/Modules/AmiSce/SceWin/X64; (INT)SceWin_5_03_1112
LnxLib 32:
NvramLibLnx.lib => \$/AptioV/RomUtils/Eta2/Binary/Modules/NvramLib/NvramLibLnx/Ia32;
(INT)NvramLibLnx-1.0.2_8
SceLnxLib32.lib => \$/AptioV/RomUtils/Eta2/Binary/Modules/AmiSce/SceLnx/Ia32; (INT)SceLnx_5_03_1112
LnxLib 64:
NvramLibLnxX64.lib => \$/AptioV/RomUtils/Eta2/Binary/Modules/NvramLib/NvramLibLnx/X64;
(INT)NvramLibLnx-1.0.2_8
SceLnxLib64.lib => \$/AptioV/RomUtils/Eta2/Binary/Modules/AmiSce/SceLnx/X64; ((INT)SceLnx_5_03_1112

Ver. 5.09.03.1470

2017-09-11

New Features

- [WINGUI] Added support ApolloLake platform flash.[EIP352902]

Ver. 5.09.03.1466

2017-09-04

Issues Fixed

- Fixed issue where tool will have a chance to search scope which is over than original setting and will be crashed when using command /r or /rn.[EIP353984].
- [WINGUI] Fixed issue where entering password will cause system feedback incorrect issue.[EIP351719]

Ver. 5.09.03.1456

2017-08-17

Rule Changes

- Changed that the system will not look for ACPI table whether is support or not before using WSMT.[EIP354442, EIP346731]

Ver. 5.09.03.1452**2017-08-02****Issues Fixed**

- [LNX] Fixed AFU run in Linux, copy driver will need copy driver's file permissions.

Ver. 5.09.03.1448**2017-07-28****New Features**

- Fixed issue where FaultToleranceFlash will be flashed to the wrong block.

Rule Changes

- Changed that command /CAF removed to write back _FVH command /caf.

Ver. 5.09.03.1445**2017-07-20****New Features**

- Added OEMCMD command.[EIP334724]
- Added that PLDM will not generate a PldmData.bin when the platform does not support BCP (BiosConfigPreserve) module.[EIP346731]
- Added that PLDM will not generate a PldmData.bin when platform supports BCP (BiosConfigPreserve) module and Token ENABLE_FV_BCP_SUPPORT = 1.
- [LNX] Added that Linux Kernel CONFIG_IO_STRICT_DEVMEM is enabled for which AFU can do the mapping. [EIP340357]

Rule Changes

- Changed AFU will not calculate FID again when OA key in NCB. [EIP325353]
- Changed only GetPattern can be enabled in the block of BIOS flash. [EIP326007]
- Changed that AFU can support Block size is over 64KB with above 32MB BIOS by structure of sROMInfoEX. [EIP340328]
- Changed that the system will look for ACPI table whether is support or not before using WSMT.
- Changed that cannot use SMI for updating OA to ACPI table directly under WSMT state. [EIP333352, EIP340049]
- Changed that PLDM fail error message.
- Changed that it is no function for command /reboot or /shutdown when combines /capsule or/recovery together.

Issues Fixed

- Fixed issue where an error of ME detection on APL platform.
- Fixed issue where when FaultToleranceFlash is enabled in APL which will execute the process of FaultToleranceFlash.

Ver. 5.09.02.1396**2017-05-25****Rule Changes**

- [LNX] Updated 'cp -f ./amifldr_mod.o ./amifldr_mod' change to 'cp -f --preserve=all ./amifldr_mod.o ./amifldr_mod'.Issues Fixed

Ver. 5.09.02.1384**2017-05-05****New Features**

- Added 64 MB ROM support, but need to have new version of SMIFlash module. [EIP308819, EIP314202, EIP297537, EIP297539]
- Added when detect multi-ROM ID, AFU will only adopt the ROM ID data of boot block.
- Added Apollo Lake Normal Flash and Fault Tolerance Flash. [EIP314749]

Rule Changes

- Changed the error message of ROM layout change.
- Update ROM layout checking rule if the FFS header is not matched, which will continue to compare with FFS data. [EIP327457]
- Modified the description of error code 0xB6 0xB7 0xBF.

Issues Fixed

- Fixed issue where cannot inspect smaller block size of every flash during verification phase. [EIP306554].
- Fixed issue where command /r and /rn cannot preserve data. [EIP327552]
- Fixed issue where flashing NCB will not be ended when have error.
- Fixed issue where PLDM cannot be workable for some RC related options. [EIP314849]
- Fixed issue where cannot update OA3 when the /A is an optional command. [EIP331115]

Ver. 5.09.01.1319**2017-01-13****Issues Fixed**

- [LNX] Fixed issue AFU driver can't remove.

Ver. 5.09.01.1317**2017-01-13****New Features**

- Added WSMT support.
- [LNX] Added PLDM support into Linux.

Rule Changes

- Changed NCB /K /Kn for which when detecting to use a BIOS, AFU will flash the BIOS by using secure flash to upload the verification.
- Changed RomHole /R /Rn for which when detecting to use a BIOS, AFU will flash the BIOS by using secure flash to upload the verification.

Issues Fixed

- Fixed issue where using AFU types file name without any command, AFU will automatically use command /p as the default setting but will not execute getpattern.
- Fixed Kn issue where when the size of bin file is bigger than Block size, AFU will only flash the data of bin file which equals the data of block size. Others, will be ignored.
- Fixed PLDM issue where AFU cannot execute when system cannot look for smi variable.

Functions Improved

- Improved the solution of search cap header. [EIP304238]

Ver. 5.09.00.1284**2016-11-01****New Features**

- Added getpattern check function.[EIP250565]
- Added DPC command which can skip A4 and A5 check.[EIP273186]
- Added COPY ROM TO ESP DISK function.[EIP247139]
- Added secure boot error ID.[EIP247139]
- [WIN]Added PLDM module into AFU.[EIP277472]
- [WINGUI] Added multi-language, Traditional Chinese, Simplified Chinese, and Korean, for AFUWINGUI.[EIP253971][EIP259139]
- [LNX]Added flash support when Linux secure boot enable.[EIP248314]

Rule Changes

- Changed Help menu to added /makedrv and /gendrv.

Issues Fixed

- Fixed issue where system has FFS check sum error when insufficient size of FV.[EIP268717]
- Fixed issue where /caf command has to add _FVH.[EIP271440]

Ver. 5.08.02.1189**2017-04-27****New Features**

- Added support more ME region.[EIP256965].

Rule Changes

- Changed the file size of modifying MEUL as the size of default memory of MEUL.

Issues Fixed

- Fixed issue where MEUL CAPSULE does not execute normally.
- Fixed issue where when BIOS does not include SLP Key, the function of checking SLP will inspect the size, which results in AFU crash. [EIP258017][EIP258384][EIP258901][EIP257903]
- Fixed issue where AFU cannot write verify when Block size is 64KB. [EIP242783]
- Fixed issue where always display Error of 0x4A when using /hole:<GUID>. [EIP259374]
- Fixed issue where cannot Write and Verify when inspect Data is Aligment.
- [WINGUI] Fixed issue where AFUWINGUI cannot get Core Version, Project Version, Firmware ID, and Firmware GUID.
- [WINGUI] Fixed issue where the boundary of right side interface in Windows 10 by AFUWINGUI.
- [WINGUI] Fixed issue where AFUWINGUI Copyright is 2016.
- [LNX] Fixed issue where the error of Linux when using /makedrv and /gendrv.

Ver. 5.08.01.1167**2017-04-27****Issues Fixed**

- Fixed issue where /hole:<SLP GUID> always replies an error of 0x4B Error: SLP key is not empty at all. [EIP254169]
- Fixed issue where GetPattern will not display the error message.
- Fixed issue where tool cannot update MSDN immediately when OA3.0 using FID location. [EIP253279]
- [WINGUI]Fixed issue where AFUWIN using /A will result in system crash issue. [EIP253279].

Ver. 5.08.01**2016-02-26****New Features**

- Added ETA_BUILD Usagehead which can add a string of "Manufacture".
- Added error message of write-once. [EIP243432]
- Added SKL platform which can use PS2 keyboard to input password in EFI.
- Added /A and /OAD which add 2+2mode.
- [LNX] Added to support ubuntu 15.10 which can generate a flash driver. [EIP247183]
- [WINGUI] Added AFUWINGUI can identify windows 10.

Rule Changes

- 01. Changed Usagehead from 2015 to 2016.
- 02. Changed /I /In /hole:<guid> /a command which adds feature of write-once. [EIP243432]
- 03. Changed search solution of SMBIOS DATA from originally searching Main block and Boot block to expanding to search all of ROM DATA. [EIP234657].

Issues Fixed

- Fixed issue where /p /b detect SLP Data whether is NULL or not.
- Fixed issue where sending twice smi0x20/0x24 when recovery and capsule. [EIP248734]
- Fixed issue where AFU results in memory overloading by ME DATA Check when ROM file is less than FLASH_PAGE_SIZE. [EIP225601]
- Fixed issue where simultaneously Buffering will make the wrong size simultaneously which results in wrong data of Flash buffer. [EIP232707]
- Fixed issue where Verify module cannot show ROM size fail.
- Fixed issue where 2+2Mode cannot pass through verification of Secure flash.
- Fixed issue where system cannot stop when GetPatternrom finds out errors.
- [LNX] Fixed issue where Get ACPI TABLE cannot find out the error of DSTD TABLE during LINUX UEFI BOOT. [EIP233270]
- [EFI] Fixed issue where getting the wrong size due to free memory in advance when EFI in Get ACPI Table. [EIP238562]
- [WINGUI] Fixed issue where system will not do "Exit button Disable" during WINGUI auto run.

Ver. 5.08.00**2015-06-26****New Features**

- Add support Check ACPI Table "BIMC" would run 2x2 mode.[EIP179199]
- Add support SmiFlash_17;[EIP204308]
- Add supports ME capsule update function.[EIP205035]
- Add support OFBD MFG control..

Rule Changes

- Changed more condition to identify the SLP2.0 key is empty or not.[EIP215239].

Issues Fixed

- Fixed OFBD Get Pattern of Rom File would show other error message.[EIP204355]
 - Fixed /cmd:{xxx} command can't use issue.[EIP215444]
-

Ver. 5.07.01**2015-02-03****New Features**

- Add error message for OEM CMD Checking module.
- Add support SMBIOS data in FV_DATA.
- Add support /cmd: command.
- Add support watchdog value restore.[EIP197706]

Rule Changes

- Changed command: "/OAD", remove upload bin file to BIOS verify step.[[MY6] AFU tool /OAD fail]

Issues Fixed

- Fix oemcmd and cmd together use have crash issue.
- Fix oem get pattern of rom file debug message have not disabled.
- Fix Windows driver.

Ver. 5.07.00**2014-11-18****New Features**

- Add new's command /JBC.[EIP174535].
- Add new's command /MEUL.[EIP174535].
- Add new's feature /Recovery:<Path>, AFU will copy rom file to specified directory.(Rom file can't auto delete.)
- Add new's OFBD module Get Pattern Module.[EIP159961]
- Add new's capsule:0 ,AFU run capsule mode will enable shutdown step.
- Add support Android OS AFU Linux Version.[EIP159621]
- Add new hide command /b2.[EIP164320]

Rule Changes

- Changed disable all hide commands.
- Changed command: "/d", show capsule header check string, form "ok/fail" to "Enable/Disable"
- Changed printf flash message way, reduce the frequency of use of printf function.
- Changed init platform step, AFU will priority use "Runtime memory hole".
- [WIN] Changed add check driver version function.
- [WIN] Changed AFU only delete windows driver made by UCP produced, It will not delete all driver.

Issues Fixed

- Fix Aptio5 rom file have many _FVH string, it will cause AFU check FFS error.
- Fix AFU can't show OFBD_CFG BIOS report error.
- Fix update SLP key AFU will modify ffs attribute issue, this issue will cause secure flash verify fail.[EIP162159]
- Fix rom file check sum will cause AFU execute crash.
- Fix hide command "/cmd:" /Axxx.bin + /cmd:{xxx} issue.
- Fix hide command "/oemcmd:" /Axxx.bin + /oemcmd:xxx issue.
- [WIN] Fix when use UCP add driver into AFU. From another directory call AFU, It will decompress into wrong directory, cause AFU can't find driver.
- [WINGUI] Fix AFUWINGUI use command /LR will show error message issue.
- [WINGUI] Fix AFUWINGUI have add rom file and add command. In command line, input command run AFUWINGUI, it will show Unknown command message box.

Ver. 5.06.01**2014-04-25****New Features**

- Add check Aptio platform's feature.
- Add new egm command sfmdt:n1:n2.[EIP151370]
- Add new egm command preset:n.
- Add new command /MEUL.

Rule Changes

- Changed After flash error, afu will add blank line continue print error message.

Issues Fixed

- Fix Alignment RomHole block issue bring SLP2.0 offset calculate error.
- [WIN] Fix when use UCP adding windows driver to AFU inside, afu will decompress to error path.

New Message

- Error: Using the wrong AFU version, Please use Aptio 4 AFU.
- Error: Using the wrong AFU version, Please use Aptio 5 AFU.

Ver. 5.06.00**2014-03-24****Rule Changes**

- Changed Copyright to 2014.
- Changed when use command /In, AFU check platform have not rom hole, AFU will show, "Error: Rom Hole not exist."

Issues Fixed

- Fix ECX erase size issue.[EIP105071].
- Fix UCP insert ROM file AFU can't open issue.
- Fix command /OAD can't flash issue, when secure flash enable.
- Fix, AFU can't find FID OA key issue, when ROM data have many _FVH string.
- Fix When NVRAM is full, and SMBIOS data in NVRAM, AFU can't preserve this data.
- Fix When flash /p /b /n add /me command, AFU will not preserve need preserve data.
- Fix When ROM Hole size exceed two block size, /holeout bin file is not right data.
- Fix When new rom Rom Hole offset different old rom rom hole offset, use /p /b /n /In, In rom hole data will be update to old rom offset.[EIP157284]

Change Message

- "Error: OA Data invalid." to "Error: OA key data is invalid."
- "Error: OA key is not NULL at all. And OA Key is the same as Bin File in system." to "Error: OA key is not empty at all. And OA Key is the same as Bin File in system."
- "Error: OA key is NULL at all already." to "Error: OA key is empty at all already."
- "Error: OA key is not NULL at all. And OA Key is no the same as Bin File in system." to "Error: OA key is not empty at all. And OA Key is no the same as Bin File in system."
- "Error: Unable to start a Secure Flash session." to "Error: Secure Flash Rom Verify fail."

Ver. 5.05.04**2014-01-24****Issues Fixed**

- Fix SMBIOS Data can't restore, when SMBIOS Data in NVRAM and NVRAM is full.
[EIP145538],[EIP145305]

Ver. 5.05.03**2013-11-12****Rule Changes**

- Change Version 3.05.02 to 5.05.03.

Issues Fixed

- Fix check EC bin file header data return result error.
- Fix Rom Hole does not Alignment block error.[EIP143348]
- [WINGUI] Fix WINGUI Show OFBD ROM ID Check dialog issue.[ECR191374]
- [WINGUI]Fix WINGUI Show OFBD EC dialog issue.