

Intel® Management Engine BIOS Extension 11.0.0.0005 Release Notes

Intel® 10 Series Express Chipset

May 2015

Intel Confidential

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an order number and are referenced in this document, or other Intel literature, may be obtained by calling 1-800-548-4725, or go to:
http://www.intel.com/design/literature.htm%20

This document contains information on products in the design phase of development.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others.

Copyright © 2014-2015 Intel Corporation. All rights reserved

Revision History

Date	Revision
April 03, 2014	11.0.0.0001
August 01, 2014	11.0.0.0002
March 04, 2015	11.0.0.0003
March 14, 2015	11.0.0.0004
May, 2015	11.0.0.0005

New Features

New Features (or changes) in < Build name and number>	
Reference No.	**Description**
New Features in Intel® Management Engine BIOS Extension 11.0.0.0001	
N/A	Intel® MEBX 11.0.0.0001 is compatible with firmware 11.0.0.0053 or later
New Features in Intel® Management Engine BIOS Extension 11.0.0.0002	
N/A	Intel® MEBX 11.0.0.0002 is compatible with firmware 11.0.0.0053 or later
2281409	SKL SDS - Add HECI3 communication support for Integrated Touch
2281612	USB-R Storage Redirection added in MEBx menu
New Features in Intel® Management Engine BIOS Extension 11.0.0.0003	
N//A	Intel® MEBX 11.0.0.0003 is compatible with firmware 11.0.0.1115 or later
New Features in Intel® Management Engine BIOS Extension 11.0.0.0004	
N//A	Intel® MEBX 11.0.0.0004 is compatible with firmware 11.0.0.1115 or later
New Features in Intel® Management Engine BIOS Extension 11.0.0.0005	
N/A	Intel® MEBX 11.0.0.0004 is compatible with firmware 11.0.0.1115 or later

NOTE:

"Intel® ME firmware version format (X.X.X.XXXX) includes major, minor, hotfix and build versions. When MEBX release note points out certain ME firmware version or later, the "later" means all later ME firmware version which includes "hotfix" and "build" versions based on the same "major" and "minor" versions. For example, if MEBX release note says MEBX is compatible with 11.0.0.1115 or later, it means the current MEBX can work with later ME11.0 (same major and minor version) firmware including 11.0.1.XXXX or 11.0.2.XXXX and so on

Resolved Issues

Resolved Issues in <Build name and Number>	
Reference No.	***Description***
Issues Resolved in Intel® Management Engine BIOS Extension 11.0.0.0001	
N/A	*Initial release*
Issues Resolved in Intel® Management Engine BIOS Extension 11.0.0.0002	
5318853	*Fixed MEBx entry point doesn't check for SKU type which causes some unnecessary code to be executed on consumer SKU*
N/A	*Merging Intel® Management Engine BIOS Extension version 10.0.0.0006 and 10.0.0.0007 fixes to Sunrise Point (SPT)*
Issues Resolved in Intel® Management Engine BIOS Extension 11.0.0.0003	
5636942	*Fixed endless global reset loop happens after RTC clear.*
5637173	*Fixed Mebx unprovisioning functions return EFI_SUCCESS when timeout is reached.*
Issues Resolved in Intel® Management Engine BIOS Extension 11.0.0.0004	
5637589	*Fixed ME11 - MEBx : Obsolete Copyright*
2505697	*Remove unreferenced string definitions from Mebx*
Issues Resolved in Intel® Management Engine BIOS Extension 11.0.0.0005	
1205640278	*Fixed MEBx to send CPU Brand Class to ME if CPU is detected*